

3/PRB

09/744645

JC02 Rec'd PCT/PTO 26 JAN 2001

PCT/RO00/00011

Method and circuits for controlling the power of an electronically switched two-phase reluctance machine

The invention relates to electronically switched, two-phase reluctance machines (motors or generators, also called SR machines – switched reluctance machines) which have a particular magnetic circuit as known, for example, from the international patent applications WO 96/09683 and WO 98/23024.

Fig. 1 shows such a simple but operative motor, for an easier understanding in a compressed form (magnetic circuit and circuit). Each individual of the eight main windings (112) and secondary windings (113) is represented as an inductive resistor fixed on the sketched magnet yoke 11. The main current paths (see „definitions“) are represented by fat lines. The simplest circuit (see fig. 1) of an uncontrolled SR motor works in the sense of the invention, as known from the prior art, with a Hall sensor 31 with two complementary „flip-flop“ open-collector outputs 312-313 as phase control which has been realistically sketched in the vicinity of the rotor. The gate electrodes of the power switches 21X, 21Y, which receive voltage for example over a polarization pull-up resistor 35, are alternately short-circuited to the minus potential (ground) over the Hall sensor outputs 312, 313 so that the main current is thus interrupted. For an uncontrolled motor, the phase X receives current at the electrical angle 0°, see fig. 3 for example, and at 180° its main current is interrupted ; simultaneously, the Y-phase receives current, namely up to 360° (= 0°) so that the electric cycle is closed. The observance of the electric switching points (phase commutation) which correspond to the tooth-to-tooth movement of the rotor is important so that the stator 111 which comes close and the rotor poles 121 can attract each other efficiently, see fig. 1, phase X.

#### DEFINITIONS

To simplify, in the course of the specification, the semiconductor components such as the MOS-FETs, the IGBTs which conduct the main current from the source of current to the windings are called „power switches“.

09/744645

Under main current, in the sense of the invention, we understand the current which flows from the source to the windings over a power switch. The flow duration of the main current is the same as the phase duration  $T$  under full load (flip-flop operating mode of the power switches) and, considered as an electrical angle, amounts to  $180^\circ$ . The phase commutation is carried out by means of a rotor position indicator 32 which rotates in front of one or several rotor position Hall sensors 31.

Fig. 2 shows an outline of the arrangement of a few components which are relevant to the invention with the signal forms for the motor control which appear in the course of the invention.

As „phase control“, see fig. 2, we understand the circuit parts which control the phase commutation in flip-flop mode. This mode must take place in the rotor positions in which the efficiency of the commutation electrical/mechanical energy is optimal for the predetermined operating parameters.

Although a slight power control can also be achieved over the phase control adjustment, in the sense of the invention, we understand hereunder a reduction of the main current running periods over shorter gate pulses. This means that the circuit parts which form gate control signals from rotor position signals which are rectangular and have a duration less than the phase length, as represented in fig. 2 on the right, belong to the power control.

The diodes which feed the self inductance voltage  $U_a$  which occurs at the connection between the power switches and the windings during the interruption of the main current (the demagnetization energy or bypass current  $I_b$ ) to the subsequent phase are called „by-pass diodes“. „Phase angle  $w$ “ (electrical =  $180^\circ$ , mechanical =  $180^\circ$ , number of the rotor teeth) is the rotor angle which is passed through between two phase commutations, i.e. between two switching operations of the phase control (Hall sensor).

„To-to-tooth“ or „aligned position“ is the relative rotor-to-stator position in which the rotor 2 rotates in case continuous current flows continuously through a phase (minimal reluctance).

The aim of this invention is to indicate possibilities of the power control of said SR machines without additional expensive power semiconductors. It should be considered here that the efficiency of the machine should remain as high as possible. This means that the recovery of the demagnetization energy should take place efficiently and that the losses of the power electronics should be minimized.

The aim of the invention is achieved according to the teaching of the main claim. The skilled in the art are given a choice of simple circuit indications and examples in order to combine them like modules when configuring an appropriate circuit alternative in order to realize a concrete target in the sense of the invention. Under „power control“ of a SR machine, especially of a motor, we understand in the sense of the invention the reduction of the main current by appropriate short-time locking within the phase duration (the phase angle). This causes the reduction of the main current angle to less than  $180^\circ$  or that the reduction of the relative duty cycle of the power switches. This means that for the control both power switches do not work in push-pull mode („flip-flop“) any longer. Fig. 5 shows the relevant control signals of the motor as rectangular (voltage) pulses. The corresponding paths of the main current  $I_p$  (fat lines) or of the by pass current  $I_b$  (dotted line) are represented superimposed. The form of the pulses in controlled mode is represented on the right side (from  $360^\circ$ ), those in uncontrolled (flip-flop) mode on the right side ( $0-180^\circ$ ).

Because of the magnet circuits known from the prior art which allow a very simple, highly efficient recovery of the demagnetization energy of a just switched-off phase, up to now the instantaneous supplying of the second motor phase with current had to take place at the moment of the switching-off of the first one (flip-flop mode ; „interlinking“ of the phases over the bypass current).

In order to achieve a power control, it has been proposed there to interrupt the main current before the end of the phase. The current flow in this phase to be switched-off should be maintained up to the end of the phase duration due to the feedback of the self-induction voltage  $U_a$  by means of two additional power transistors 211, see WO 96/09683, pages 8-9, fig. 6e. These power transistors 211 were also necessary in case of a regulation by the known pulse width modulation.

If a feedback of the self-induction voltage over the transistors 211 would have been renounced to, this would have resulted in a waste further transmission of the bypass current to the other phase at the wrong moment, with serious consequences for the efficiency. Up to now it was thus not possible, without additional expenditure of power electronics, to realize a power control based on the reduction of the duty cycle of the power switches 21.

A simpler solution is possible according to the teaching of this invention, even if there are no flyback power transistors 211 (see WO 96/09683, fig. 6e) which supplied, at the end of the phase duration, the demagnetization energy for the locking of a power switch 21X to the phase X from which they come, as follows.

After the start of the motor which always takes place in the "flip-flop" operating mode (fig. 3, left side) of the power switches, the main current can be delayed by a fixed or variable space of time by maintaining locked the power switches 21X, 21Y after the phase commutation (see fig. 3, on the right), this space of time corresponding to an electrical angle depending on the number of revolutions of the motor. The main current of the phase X thus does not start at  $360^\circ$  any longer but starts delayed at  $360^\circ + v^\circ$ , that of the Y phase at  $540^\circ + v^\circ$ . The locking of the power switches takes place as before at  $nx180^\circ$ . This means that the occurrence of the self-induction voltage  $U_a$  (of the bypass current  $I_b$  at the end of the phase) always takes place at  $nx180^\circ$ , i.e. at a relative position of the stator/rotor teeth 111-121 in which they can efficiently attract each other efficiently, see phase X in fig. 1. The demagnetization energy (the bypass current  $I_b$ , path see fig. 3 dotted line) can thus be supplied to the following phase over the bypass diode 22 with an useful effect (as magnetizing current, accompanied by a torque), even if the main current has not yet started to flow. If the main current  $I_p$  begins to flow delayed after the time  $t$  (electrical rotor angle  $v$ ), its rise becomes steeper, since the corresponding magnet yoke 11 is already premagnetized over the bypass current. This means that an appropriate locking of the power switch 21 of the Y phase can be used for example in order to obtain an appropriate premagnetization of the Y phase over the diode 22X because of the "interlinking" of the phases over the bypass current. Because of the control of this phase switching processes, besides a power control, a certain

004551  
004552  
004553  
004554  
004555  
004556  
004557  
004558  
004559  
004560  
004561  
004562  
004563  
004564  
004565  
004566  
004567  
004568  
004569  
004570  
004571  
004572  
004573  
004574  
004575  
004576  
004577  
004578  
004579  
004580  
004581  
004582  
004583  
004584  
004585  
004586  
004587  
004588  
004589  
004590  
004591  
004592  
004593  
004594  
004595  
004596  
004597  
004598  
004599  
004600  
004601  
004602  
004603  
004604  
004605  
004606  
004607  
004608  
004609  
004610  
004611  
004612  
004613  
004614  
004615  
004616  
004617  
004618  
004619  
004620  
004621  
004622  
004623  
004624  
004625  
004626  
004627  
004628  
004629  
004630  
004631  
004632  
004633  
004634  
004635  
004636  
004637  
004638  
004639  
004640  
004641  
004642  
004643  
004644  
004645  
004646  
004647  
004648  
004649  
004650  
004651  
004652  
004653  
004654  
004655  
004656  
004657  
004658  
004659  
004660  
004661  
004662  
004663  
004664  
004665  
004666  
004667  
004668  
004669  
004670  
004671  
004672  
004673  
004674  
004675  
004676  
004677  
004678  
004679  
004680  
004681  
004682  
004683  
004684  
004685  
004686  
004687  
004688  
004689  
004690  
004691  
004692  
004693  
004694  
004695  
004696  
004697  
004698  
004699  
004700  
004701  
004702  
004703  
004704  
004705  
004706  
004707  
004708  
004709  
004710  
004711  
004712  
004713  
004714  
004715  
004716  
004717  
004718  
004719  
004720  
004721  
004722  
004723  
004724  
004725  
004726  
004727  
004728  
004729  
004730  
004731  
004732  
004733  
004734  
004735  
004736  
004737  
004738  
004739  
004740  
004741  
004742  
004743  
004744  
004745  
004746  
004747  
004748  
004749  
004750  
004751  
004752  
004753  
004754  
004755  
004756  
004757  
004758  
004759  
004760  
004761  
004762  
004763  
004764  
004765  
004766  
004767  
004768  
004769  
004770  
004771  
004772  
004773  
004774  
004775  
004776  
004777  
004778  
004779  
004780  
004781  
004782  
004783  
004784  
004785  
004786  
004787  
004788  
004789  
004790  
004791  
004792  
004793  
004794  
004795  
004796  
004797  
004798  
004799  
004800  
004801  
004802  
004803  
004804  
004805  
004806  
004807  
004808  
004809  
004810  
004811  
004812  
004813  
004814  
004815  
004816  
004817  
004818  
004819  
004820  
004821  
004822  
004823  
004824  
004825  
004826  
004827  
004828  
004829  
004830  
004831  
004832  
004833  
004834  
004835  
004836  
004837  
004838  
004839  
004840  
004841  
004842  
004843  
004844  
004845  
004846  
004847  
004848  
004849  
004850  
004851  
004852  
004853  
004854  
004855  
004856  
004857  
004858  
004859  
004860  
004861  
004862  
004863  
004864  
004865  
004866  
004867  
004868  
004869  
004870  
004871  
004872  
004873  
004874  
004875  
004876  
004877  
004878  
004879  
004880  
004881  
004882  
004883  
004884  
004885  
004886  
004887  
004888  
004889  
004890  
004891  
004892  
004893  
004894  
004895  
004896  
004897  
004898  
004899  
004900  
004901  
004902  
004903  
004904  
004905  
004906  
004907  
004908  
004909  
004910  
004911  
004912  
004913  
004914  
004915  
004916  
004917  
004918  
004919  
004920  
004921  
004922  
004923  
004924  
004925  
004926  
004927  
004928  
004929  
004930  
004931  
004932  
004933  
004934  
004935  
004936  
004937  
004938  
004939  
004940  
004941  
004942  
004943  
004944  
004945  
004946  
004947  
004948  
004949  
004950  
004951  
004952  
004953  
004954  
004955  
004956  
004957  
004958  
004959  
004960  
004961  
004962  
004963  
004964  
004965  
004966  
004967  
004968  
004969  
004970  
004971  
004972  
004973  
004974  
004975  
004976  
004977  
004978  
004979  
004980  
004981  
004982  
004983  
004984  
004985  
004986  
004987  
004988  
004989  
004990  
004991  
004992  
004993  
004994  
004995  
004996  
004997  
004998  
004999  
005000  
005001  
005002  
005003  
005004  
005005  
005006  
005007  
005008  
005009  
005010  
005011  
005012  
005013  
005014  
005015  
005016  
005017  
005018  
005019  
005020  
005021  
005022  
005023  
005024  
005025  
005026  
005027  
005028  
005029  
005030  
005031  
005032  
005033  
005034  
005035  
005036  
005037  
005038  
005039  
005040  
005041  
005042  
005043  
005044  
005045  
005046  
005047  
005048  
005049  
005050  
005051  
005052  
005053  
005054  
005055  
005056  
005057  
005058  
005059  
005060  
005061  
005062  
005063  
005064  
005065  
005066  
005067  
005068  
005069  
005070  
005071  
005072  
005073  
005074  
005075  
005076  
005077  
005078  
005079  
005080  
005081  
005082  
005083  
005084  
005085  
005086  
005087  
005088  
005089  
005090  
005091  
005092  
005093  
005094  
005095  
005096  
005097  
005098  
005099  
005100  
005101  
005102  
005103  
005104  
005105  
005106  
005107  
005108  
005109  
005110  
005111  
005112  
005113  
005114  
005115  
005116  
005117  
005118  
005119  
005120  
005121  
005122  
005123  
005124  
005125  
005126  
005127  
005128  
005129  
005130  
005131  
005132  
005133  
005134  
005135  
005136  
005137  
005138  
005139  
005140  
005141  
005142  
005143  
005144  
005145  
005146  
005147  
005148  
005149  
005150  
005151  
005152  
005153  
005154  
005155  
005156  
005157  
005158  
005159  
005160  
005161  
005162  
005163  
005164  
005165  
005166  
005167  
005168  
005169  
005170  
005171  
005172  
005173  
005174  
005175  
005176  
005177  
005178  
005179  
005180  
005181  
005182  
005183  
005184  
005185  
005186  
005187  
005188  
005189  
005190  
005191  
005192  
005193  
005194  
005195  
005196  
005197  
005198  
005199  
005200  
005201  
005202  
005203  
005204  
005205  
005206  
005207  
005208  
005209  
005210  
005211  
005212  
005213  
005214  
005215  
005216  
005217  
005218  
005219  
005220  
005221  
005222  
005223  
005224  
005225  
005226  
005227  
005228  
005229  
005230  
005231  
005232  
005233  
005234  
005235  
005236  
005237  
005238  
005239  
005240  
005241  
005242  
005243  
005244  
005245  
005246  
005247  
005248  
005249  
005250  
005251  
005252  
005253  
005254  
005255  
005256  
005257  
005258  
005259  
005260  
005261  
005262  
005263  
005264  
005265  
005266  
005267  
005268  
005269  
005270  
005271  
005272  
005273  
005274  
005275  
005276  
005277  
005278  
005279  
005280  
005281  
005282  
005283  
005284  
005285  
005286  
005287  
005288  
005289  
005290  
005291  
005292  
005293  
005294  
005295  
005296  
005297  
005298  
005299  
005300  
005301  
005302  
005303  
005304  
005305  
005306  
005307  
005308  
005309  
005310  
005311  
005312  
005313  
005314  
005315  
005316  
005317  
005318  
005319  
005320  
005321  
005322  
005323  
005324  
005325  
005326  
005327  
005328  
005329  
005330  
005331  
005332  
005333  
005334  
005335  
005336  
005337  
005338  
005339  
005340  
005341  
005342  
005343  
005344  
005345  
005346  
005347  
005348  
005349  
005350  
005351  
005352  
005353  
005354  
005355  
005356  
005357  
005358  
005359  
005360  
005361  
005362  
005363  
005364  
005365  
005366  
005367  
005368  
005369  
005370  
005371  
005372  
005373  
005374  
005375  
005376  
005377  
005378  
005379  
005380  
005381  
005382  
005383  
005384  
005385  
005386  
005387  
005388  
005389  
005390  
005391  
005392  
005393  
005394  
005395  
005396  
005397  
005398  
005399  
005400  
005401  
005402  
005403  
005404  
005405  
005406  
005407  
005408  
005409  
005410  
005411  
005412  
005413  
005414  
005415  
005416  
005417  
005418  
005419  
005420  
005421  
005422  
005423  
005424  
005425  
005426  
005427  
005428  
005429  
005430  
005431  
005432  
005433  
005434  
005435  
005436  
005437  
005438  
005439  
005440  
005441  
005442  
005443  
005444  
005445  
005446  
005447  
005448  
005449  
005450  
005451  
005452  
005453  
005454  
005455  
005456  
005457  
005458  
005459  
005460  
005461  
005462  
005463  
005464  
005465  
005466  
005467  
005468  
005469  
005470  
005471  
005472  
005473  
005474  
005475  
005476  
005477  
005478  
005479  
005480  
005481  
005482  
005483  
005484  
005485  
005486  
005487  
005488  
005489  
005490  
005491  
005492  
005493  
005494  
005495  
005496  
005497  
005498  
005499  
005500  
005501  
005502  
005503  
005504  
005505  
005506  
005507  
005508  
005509  
005510  
005511  
005512  
005513  
005514  
005515  
005516  
005517  
005518  
005519  
005520  
005521  
005522  
005523  
005524  
005525  
005526  
005527  
005528  
005529  
005530  
005531  
005532  
005533  
005534  
005535  
005536  
005537  
005538  
005539  
005540  
005541  
005542  
005543  
005544  
005545  
005546  
005547  
005548  
005549  
005550  
005551  
005552  
005553  
005554  
005555  
005556  
005557  
005558  
005559  
005560  
005561  
005562  
005563  
005564  
005565  
005566  
005567  
005568  
005569  
005570  
005571  
005572  
005573  
005574  
005575  
005576  
005577  
005578  
005579  
005580  
005581  
005582  
005583  
005584  
005585  
005586  
005587  
005588  
005589  
005590  
005591  
005592  
005593  
005594  
005595  
005596  
005597  
005598  
005599  
005600  
005601  
005602  
005603  
005604  
005605  
005606  
005607  
005608  
005609  
005610  
005611  
005612  
005613  
005614  
005615  
005616  
005617  
005618  
005619  
005620  
005621  
005622  
005623  
005624  
005625  
005626  
005627  
005628  
005629  
005630  
005631  
005632  
005633  
005634  
005635  
005636  
005637  
005638  
005639  
005640  
005641  
005642  
005643  
005644  
005645  
005646  
005647  
005648  
005649  
005650  
005651  
005652  
005653  
005654  
005655  
005656  
005657  
005658  
005659  
005660  
005661  
005662  
005663  
005664  
005665  
005666  
005667  
005668  
005669  
005670  
005671  
005672  
005673  
005674  
005675  
005676  
005677  
005678  
005679  
005680  
005681  
005682  
005683  
005684  
005685  
005686  
005687  
005688  
005689  
005690  
005691  
005692  
005693  
005694  
005695  
005696  
005697  
005698  
005699  
005700  
005701  
005702  
005703  
005704  
005705  
005706  
005707  
005708  
005709  
005710  
005711  
005712  
005713  
005714  
005715  
005716  
005717  
005718  
005719  
005720  
005721  
005722  
005723  
005724  
005725  
005726  
005727  
005728  
005729  
005730  
005731  
005732  
005733  
005734  
005735  
005736  
005737  
005738  
005739  
005740  
005741  
005742  
005743  
005744  
005745  
005746  
005747  
005748  
005749  
005750  
005751  
005752  
005753  
005754  
005755  
005756  
005757  
005758  
005759  
005760  
005761  
005762  
005763  
005764  
005765  
005766  
005767  
005768  
005769  
005770  
005771  
005772  
005773  
005774  
005775  
005776  
005777  
005778  
005779  
005780  
005781  
005782  
005783  
005784  
005785  
005786  
005787  
005788  
005789  
005790  
005791  
005792  
005793  
005794  
005795  
005796  
005797  
005798  
005799  
005800  
005801  
005802  
005803  
005804  
005805  
005806  
005807  
005808  
005809  
005810  
005811  
005812  
005813  
005814  
005815  
005816  
005817  
005818  
005819  
005820  
005821  
005822  
005823  
005824  
005825  
005826  
005827  
005828  
005829  
005830  
005831  
005832  
005833  
005834  
005835  
005836  
005837  
005838  
005839  
005840  
005841  
005842  
005843  
005844  
005845  
005846  
005847  
005848  
005849  
005850  
005851  
005852  
005853  
005854  
005855  
005856  
005

current circuit in the phases can be achieved which is favourable for an optimal efficiency and/or for noise reduction.

Considering the findings of this invention, namely essentially that the reduction of the main current duration has taken place at the beginning of the phase and not at the end of the phase as in the prior art, not only the expenditure of electronics is reduced but a control is achieved in wider limits.

The variable rise-delay time  $t$  of the power switches 21 can take place electronically or over the mechanical displacement of a second Hall sensor 31a. This can be achieved electronically with a rise-delayed time function element which is set into operation at the time of the phase commutation and which holds the gate electrodes of the power switches 21 around the space of time  $t$  on the minus potential after the phase commutation (see fig. 3). This delay can take place with parameters, can thus be adjusted for example over a circuit which compares a nominal value with the actual value and correspondingly corrects it in order to maintain constant a determined controlled variable such as the number of revolutions or the torque. Thus, for an increase of the number of revolutions, the delay  $t$  should be increased in order to thus reduce the main current until the number of revolutions decreases to the set value. If the delay  $t$  is constant, a certain limitation of the number of revolutions, which however is unprecise, is achieved. If the number of revolutions increases, the relative duty cycle (the power draw) of the motor will decrease until there results a limitation of the number of revolutions. This takes place because, for a higher number of revolutions, the phase duration  $T$  decreases, while the delay  $t$  remains constant so that the relative duty cycle  $T - t$  decreases. The ratio main current angle/phase angle is reduced.

A simple power control for which this ratio remains constant can be achieved by using two phase-shifted rotor position (Hall) sensors 31 with digital open-collector outputs 312, 313 (see fig. 4). In this connection, the gate electrode of the power switches 21 is switched over the first Hall sensor (31) to the high saturation potential and short-circuited "low" to the minus potential by the second Hall sensor 31a (the outputs of which are connected in parallel).

In the lower half of fig. 4, in plane a, the signals of an output 312 of the active hall sensor 31 (control signals of the gate GN when the switch 314 is open and 315 closed) are indicated, or in plane b those of the output of the Hall sensor 31a (switch 315 open, 314 closed). In plane c, the resulting X gate signal (reduced power) is indicated, when both switches are closed. The high pulse width of the Y-phase is identical, however electrically phase-shifted by 180°. If the signals of both Hall sensors are phase-shifted by the angle  $v$ , the angle while the gate electrode is high (= main current angle) is always  $w-v$  (phase angle - phase offset of the Hall sensors).

For the motor of an electric tool, this power control can possibly be more favourable. For common manual tools, an increase of the number of revolutions takes place by further pushing of the motor close switch which is integrated into the handle which, in this case, contains a potentiometer. Such a switch can also cause, for example over a lever, the movement of a Hall sensor so that the function of the power control of the tool (see fig. 5) can be represented as follows.

Depending on the desired direction of rotation, the position for a starting sensor 31a opposite the transmitting magnet 32 is predetermined by means of the bistable left/right selection lever 36, with breakover points which are situated approximately in the first quarter of the phase angle, on the left or on the right of the neutral tooth-to-tooth position.

At the beginning of the stroke of the lever 37, the starting Hall sensor 31a is activated, as shown in fig. 3, and the motor starts in the preselected direction. After having reached the lower limit of the number of revolutions, the second Hall sensor 31 is activated which however shows the maximal angle offset  $v$  so that the main current angle is small and the motor works with a minimal power (or number of revolutions). By pushing further the lever 37, one of the Hall sensors 31 is moved, as shown in fig. 5, so that the offset  $v$  reduces so that the main current angle increases and thus the power of the motor. If the phase offset of both Hall sensors 31 is the same, the motor works at full load (the main current angle and the phase angle are the same, flip-flop mode).

For a few applications (vacuum cleaner for example), the movable Hall sensor 31 can be displaced depending on the output of a driven device (vacuum, flow, temperature, current, oscillation), for example for pressure by means of a cylinder/piston/spring device 38, what allows particularly low-cost global solutions for the control (see fig. 6).

For an internal combustion engine of a passenger car for example, which is equipped with a starter according to WO 98/23024, the oscillations of the Otto engine can be attenuated by means of a Hall sensor which is positioned free from rotary oscillations. If the Otto motor with the reluctance starter shows rotary oscillations, they result in that the Hall sensor positioned free from rotary oscillations moves relative to the oscillating stator so that the reluctance machine swings in pendulum fashion between the motor/generator (brake) mode in the sense of a reduction of the oscillations of the Otto engine.

These functions can naturally also be realized electronically so that, instead of a mechanical displacement, electrical phase offsets are used.

For the electronic solutions with time switching, it is basically a matter of controlling longer or shorter main current running periods synchronized to the instantaneous rotor/stator positions which are advantageous for converting the electrical energy into mechanical energy and of adjusting them eventually depending on a nominal parameter (for example, number of revolutions).

Thus, for the machine control, a rotor position signal must be gained which unambiguously reflects the angle of rotation and eventually the sense of rotation. This signal can be processed with known electronic means so that control pulses for the power switches 21 can be obtained in flip-flop mode (full load) or in power control mode.

Here, it is irrelevant to know which type of position sensors is used, whereby these position sensors are designated in the course of the specification as Hall sensors 31 (analog, digital, differential, programmable) to simplify the matter. The rotor teeth can be directly scanned by means of a differential or of a programmable Hall sensor so that a phase commutation signal can be obtained even without the aid of a transmitting magnet 32. The rotor position can also

卷之三

take place in the sense of the invention without the aid of a sensor by the electronic determination of the reluctance of the motor phases, as known from the prior art.

As fig. 3 shows, in which the flip-flop phase commutation signal of an uncontrolled motor and the sawtooth signal or sinusoidal signal of a rotor position transmitter are represented as a comparison, from these values not only the phase commutation signals can be gained, but also other control signals. Here, simple electronic means are used such as the Schmitt-trigger. A sawtooth signal of this type can be obtained, for example, by means of an analog Hall sensor 31c which is polarized by a permanent magnet 33 and which is situated radially in front of a soft magnetic "saw tooth disk" 32a which rotates together with the rotor (fig. 6). This being, the magnetic field which triggers the Hall sensor (the reluctance of the system) changes in the manner of saw teeth so that the output signal of the Hall sensor 31c (= input signal of the phase control trigger) also shows this form. From the sawtooth signal, a phase commutation signal (flip-flop) can be obtained over a level switch 34 (Schmitt-trigger, see fig. 2 and 3), when the trigger tilts in the middle of the rise phase (level  $U_k$ ) (phase commutation from X to Y) or falls back to the starting position when the signal decreases after the saw top  $U_s$  (Y to X), see fig. 3, compare planes a-c. Due to the adaptation of the sawtooth voltage  $U_k$ , the phase symmetry can easily be influenced without the phase position being changed (when falling back after the tooth top). Phase symmetry means that the duration of the high phases on both X

and Y outlets, thus on the gate electrodes  $G_x, G_y$  of the power switches 21X, 21Y is always the same, either in the flip-flop mode or in the power control mode. This is necessary in order to hold constant the currents of both phases for the steady operation of the machine.

However, should it, for example because of the properties of the components, come to the fact that the high phases at the gate of the power switches 21X, 21Y have a different length, it is possible, for example with the basic circuit according to fig. 7, to obtain a voltage signal  $U_d$  (symmetry difference) which is used for compensating the phase symmetry. By means of this voltage  $U_d$ , the sawtooth voltage  $U_k$  of the trigger 34 is adapted in such a way that a phase symmetry occurs. The voltage  $U_d$  is the potential difference on two capacitors

$C_x, C_y$  which are connected with the gate electrodes  $G_x, G_y$  of the power switches over the resistors  $R_x, R_y$  and which are alternately loaded and discharged and which take up a tension level which corresponds to the ratio of the on/off duration of the respective switch  $21X, 21Y$ . This phase duration signal can be used in flip-flop mode (for example during the run-up period of the machine) as well as an analog speed signal.

These possibilities of influence of the phase commutation can be completed with a dynamic, main current depending alternative (fig. 8) which can substantially improve the starting behaviour. For this purpose, one (or several) current loops 322 (see fig. 8) is inserted for example in the magnetic circuit of the transmitting magnet (32) Hall sensor (31), this current loop being passed through for example by the main current of a phase or by an appropriate control current. Depending on the momentaneous current flow direction and intensity, the magnetic field which controls the Hall sensor 31 and thus the phase commutation, is influenced so that a feedback takes place in this manner between the main current  $I_p$  and the phase commutation. Thus, a load depending shifting of the phase commutation points as feedback is possible.

Such a shifting of the phase commutation can also be carried out with phase shifting electronic means (known from the prior art) in wider spheres, when it is useful for the optimization of the efficiency or for the control of the motor. For this purpose, it is advantageous, for example, to gain a sinusoidal signal (fig. 3, plane d) from an analog Hall sensor because this signal can be processed more easily for the phase shifting. For example, the means described in connection with fig. 3 as well as the means for the phase shifting known from the prior art can be used here.

For the start of the motor, a phase commutation in the vicinity of the tooth space is advantageous, position , fig. 1, corners of the rotor and stator teeth of the X-phase ; the shifting of the phase commutation relative to this position should however increase when the number of revolutions increases. For this purpose, it is advantageous, for example, when a bigger phase shifting of the phase commutation is caused by means of a speed (voltage) signal which increases with the switching frequency and which is easy to gain. The amplitude of this

shifting will depend on the operating parameters (number of revolutions, torque) for an optimal efficiency.

A possibility to determine this is, the number of revolutions or the load being constant (controlled), to bring the phase shifting as far as the main current  $I_p$  or the bypass current  $I_b$  reaches the lowest value. The latter ( $I_b$ ) can be measured with lower losses, eventually even without losses, over the self-induction voltage  $U_a$ .

This efficiency optimization can take place automatically with an appropriate regulator circuit. If, instead of a simple sensor, a programmable Hall sensor which shows adjustable trigger components on the same chip is used, it is possible to definitely reduce the expenditure of the circuit and to control the phase shifting of the output signals with the programming of the sensor. The rotating magnetic field (the motive effect) of the machine develops from the superposition of the main current  $I_p$  and of the bypass current  $I_b$  which always arises after the interruption of the main current and which simultaneously passes through the windings of both phases.

For machines such as those which are described in WO 98/23024 which consist of two machine halves (with the same axis, mechanically offset by an angle of  $w/2$  for torque smoothing), it is possible to reduce the peaks of the self-induction voltage  $U_a$  by feeding the bypass current  $I_b$  not only to the complementary phase, thus from X to Y, but also to the phases of the second machine half, see fig. 1a. The second machine half has the same minus connection as the first one and is identical therewith. In fig. 1, the diodes 22 which are drawn in oblique dashes show the possible current paths to the secondary windings 113/power switches 21 of the second machine sketched in fig. 1a.

This means that the bypass current  $I_b$  of the X-phase is derived to the phases X and Y' (belonging to the second machine) or it is fed only to the Y-phase when this is advantageous for the efficiency. The method is the same for the bypass current  $I_b$  of the second machine half. The main current as well as the considerably weaker bypass current (see fig. 3) can be controlled, always depending on each other, in certain limits for the optimization of the motor function so that, when they are adjusted in this way, losses can be minimized.

The main losses are :

- a) Ohmic losses in windings and power switches which substantially depend on the current peaks which thus should be avoided as far as possible.
- b) Switching losses which require to avoid too many switching operations.
- c) Losses due to peaks of the self-induction voltage(depending on the current peaks) which are absorbed in avalanche mode by the power switches 21 and which endanger them.
- d) Iron losses which are connected with the losses under a) and b).

In order to achieve the best possible efficiency, it is thus necessary to obtain with as less switching operations as possible an appropriate flow of the main current  $I_p$ , i.e. especially to avoid high values at the time of the switching-off. For a few operating states, it is eventually appropriate to take an additional interruption of the main current  $I_p$  into consideration (see plane e, right side) if high current peaks are thus avoided, whereby there results as a consequence an increase of the efficiency. In this way, the current drawn from the motor has a lower ripple and the electrolytic capacitor which is eventually necessary for smoothing is smaller. Fig. 3, plane a,b shows typical flows of the main current in an uncontrolled motor or in a motor controlled only over the delay  $t$ . The current peaks  $I_s$  at the end of the phase can be reduced, for example, by the fact that the gate of the power switch 21 is short-circuited for the time  $t_3$  at the minus potential (ground at the phase position  $t_2$  (see plane a and e) where the main current  $I_p$  has a lower value, what reduces the main current especially in the rear area, see plane e. The power control guarantees that the number of revolutions does not drop and decreases to  $t_1$ , whereby the main current on the whole remains at the nominal value, however without the marked peak  $I_s$ , what can contribute to an increase of the efficiency.

In order to limit the starting current of the motor, the main current can be interrupted once or several times for a constant or parametrically variable duration  $t_3$  within the phase duration  $T$  when reaching a predetermined peak value  $I_v$  (see plane E, on the left), as shown in fig. 3, plane e. The delay to the phase beginning does not exist ( $t=0$ ). The reset of the main current can take place, for example, when the bypass current falls to a predetermined value.

This starting current limitation can also act as a protective function and takes place, for example, by means of a transistor 42, see fig. 9.

Because the beginning and the end of the phase are predetermined and the windings of the concerned yokes are continuously traversed, either by the main current or by the bypass current, this means no basic abandonment of the flip-flop starting mode.

Without this protective function, it cannot be avoided, especially when starting the motor, that the main current to be switched reaches high values. Thus, the peaks of the self-induction voltage  $U_s$  also reach very high values which, despite the bypass current  $I_b$ , exceed the electric strength of the power switches 21 (Mosfets, IGBTs). However, the energy of the voltage peaks clamped in the avalanche mode (= avalanche clamping) endangers the power switches. Therefore, it is more advantageous to convert these peaks into heat by triggering the gates, thus by the conductivity of the chips (active clamping). This is carried out by means of the circuit shown in fig. 9 where the gate will receive a positive potential over the Zener diode 40 and by locking the transistor 41 (21 becomes conducting) as soon as the voltage applied to the power switches 21 approaches the avalanche value and thus exceeds the Zener voltage.

As fig. 9 shows, the gate can be controlled over the open collector output of the Hall sensor 31 (phase control) and additionally over a series (41) or a parallel transistor 42.

The gate control can thus be disconnected from the phase control, if need be, in order to realize, for example, the most important operating and protective functions of the motors such as :

- a) Switching on and off
- b) Power control and control of the number of revolutions
- c) Overvoltage protection as well as undervoltage protection
- d) Thermal switching-off, current delimitation and short-circuit protection
- e) Protection against inductive voltage peaks as already mentioned
- f) Braking

The transistor 42 takes up protective functions and should short-circuit the gate at the minus potential in case one of the states mentioned under c) or d) occurs. From WO 96/09683, we know a reluctance machine which has no stator but two independent rotors 1, 2, whereby the first one, the field rotor 1 (similar to a rotating stator), is supplied with the main current  $I_p$  over two brushes 34 or slip rings, as shown by fig. 10.

The field rotor carries on the frame 5 the power switches 21 and a part of the phase and speed control which are thus movable for adjustment and inaccessible from outside. For this type of adjustments, it is thus necessary to carry out a contactless transmission, for example, of the externally predetermined speed nominal value which is carried out by means of an axially mounted, simultaneously rotating Hall sensor 39 which is triggered by a stationary control winding 49.

By means of these components 39, 49, it is possible, for example, to control the time base which controls the rise-delay time  $t$  of the power switches 21 (the power control) which is situated on the simultaneously rotating board 45 of the field rotor 1. The phase control rotates with the field rotor. During the adjusted delay  $t$ , the control winding 49 is supplied with current. This winding controls the Hall sensor 39 which controls said power control. Since the time base is controlled by the phase commutation, thus by the steep drop of the main current  $I_p$ , this process which is easy to recognize electronically could start an external time base. The advantages of the invention are based on the simplicity of the (power) circuits which allow a low-cost realization.

Three circuit examples (fig. 11, 12, 13), which can be used for the motor according to fig. 1, will be described hereunder for the speed control. The circuit of the motor has been represented in a simplified way and has been differently completed, depending on the example.

The two bypass diodes (in series with the bypass windings 113) have been replaced by a single diode 221 with the same function, the cathode of which is directly connected with the plus connection. For controlling, the triggering of the gate electrodes of the power switches 21 must be disconnected from the phase commutation at the beginning of the phase. In order to cause a delay, it is most

simple to combine a RC-module set into operation by the phase control with a level discriminator (trigger) so that a low signal arises at the output of the trigger during the delay  $t$ , this signal switching „low“ the gate of the power switch of the active phase of the motor. The switching-off of a phase (commutation high-low) must thus trigger the rise-delay time  $t$  of the power switch 21 of the next phase.

Fig. 11 shows a realization example of the invention between the circuit of a motor (on the left of the dashed line) and the level switch (here as a Schmitt-trigger, on the right of the dotted line). The motor with two phases X and Y has main windings 112 in series with the power switches 21 (both provided with an inverse diode) which are traversed by the main current  $I_p$ . The secondary windings 113 are traversed by the bypass current  $I_b$  which flows through the bypass diode 221 to the plus line. The gate electrodes  $G_x, G_y$  of the power switches 21 are pulled up by the resistors  $R_g$  in case the on/off switch  $ID$  is closed. They are pulled down to the minus potential by the digital hall sensor 31 with complementary (flip-flop) outputs  $H_x, H_y$  (= phase control), no longer directly but over the diodes  $D_1$ . Up to here, the function is the same as that of an uncontrolled motor.

The complementary outputs  $H_x, H_y$  of the Hall sensor 31, in front of which the transmitting magnet 32 rotates, are connected to the pull-up resistors  $R_t$  in order to obtain signals for the control. During the „high“ period of the outputs  $H_x, H_y$  of the Hall sensor 31, the capacitors  $C_t$  are charged by these resistors. The charging can be accelerated over the diodes  $D_1$  (dotted line), if need be, for improving the control behaviour.

If one of the open-collector outputs  $H_x, H_y$  of the Hall sensor 31 becomes „low“, the respective capacitor  $C_t$  discharges over this output or over the series resistor  $R_t$ , whereby the latter form RC modules ( $R_t, C_t$ ) which determine the delay  $t$  for each phase for the speed control.

During the phase commutation, an asymptotic decreasing minus potential  $U_t$  occurs at the connection  $R_t-C_t$ .

This negative voltage which comes either from the X-phase or from the Y-phase causes over the diodes  $D_e$  and the resistor  $R_e$  a current  $I_t$  which tilts the

DRAFT - 100% - 100% - 100%

Schmitt-trigger ST. Thus, the output transistor  $T_s$  becomes conducting. Thus, the respective gate electrode of the active power switch 21 remains connected with the minus potential for the time  $t$  over the diodes  $D_t$  or the transistor  $T_a$  and the low-impedance resistor  $R_1$ , even after the phase commutation, thus "low".

The delay  $t$  of the main current  $I_p$  is adjusted by the potentiometer  $P_t$  which conducts an adjustable current  $I_s$  in direction of the base of the input transistor  $T_e$  (nominal value adjustment).

The subtraction of the nominal value current  $I_s$  and of the time variable current  $I_t$  results in a resulting base current  $I_e$ . When this current reaches the threshold value, the transistor  $T_e$  becomes conducting, whereby the output transistor  $T_a$  blocks so that the respective gate of the power switches 21 can be pulled up over the resistance  $R_g$ .

The power switch 21 is thus conducting, the main current  $I_p$  thus begins to flow in the sense of the invention after the delay.

The speed control circuit (on the right of the dashed line) can be fixed on a separate board which can be connected with an uncontrolled motor (for example over a plug-in connection). The same is also valid for the circuit according to fig. 12.

At the input of the Schmitt-trigger, influence can be exerted in many ways on the base current  $I_e$  in order to improve the functions of the control or to protect the motor. Here (see arrows), a pilot current can be fed in or drawn, either in order to influence on the delay  $t$  (feedback functions for example), or to stop the motor in case of an endangering due to the permanent blocking of the input transistor  $T_e$ . The delay  $t$  (the speed of the motor) can be influenced, for example, in an appropriate way in the following situations.

As a feedback for the speed control, the number of revolutions decreases below a nominal value, the delay  $t$  is then reduced to increase the main current.

As a starting current limitation, the starting current or the self-induction voltage  $U_a$  reaches too high values, the delay  $t$  is then increased in order to lower the

main current  $I_p$ . For the temperature stabilization, the temperature of the motor increases or that of individual parts thereof, the delay  $t$  is then increased.

The number of revolutions of the motor can be determined over the switching frequency at the output of the phase control which can be eventually converted into an analog signal. At least one of the signals with a predetermined voltage at the output of the phase control is fed for this purpose (see fig. 11, below the fat dashed line) over a capacitor  $C_a$  (approximately  $0.1 \mu F$ ) to a circuit which separates the charging/discharging currents of the capacitor  $C_a$  over two diodes  $D_+$ ,  $D_-$  and feeds them by integration for charging two capacitors  $C_+$ ,  $C_-$  ( $5-1000 \mu F$ ) with parallel switched discharging resistors  $R_d$ .

The positive or negative charging of the capacitors  $C_+$  or  $C_-$  is proportional to the number of revolutions and each of these voltages can be used if need be for control purposes. If a potentiometer  $P_1$  is connected with the connection points between the diodes  $D_+$ ,  $D_-$  and the capacitors  $C_+$ ,  $C_-$  instead of the resistors  $R_{d+}$ ,  $R_{d-}$ , a (feedback) signal adjustable from positive to negative can be obtained on its cursor, this signal being proportional to the number of revolutions and whereby this signal can be supplied to the input of the Schmitt-trigger  $ST$ , for example as feedback current.

In order to cause, for example, a smooth start of the motor, the values of the discharging resistor  $R_d$  or of the capacitors  $C_+$ ,  $C_-$  are selected in such a way that one of the capacitors  $C_+$ ,  $C_-$  reaches more slowly the voltage which corresponds to the number of revolutions of the motor. The signal drawn on the potentiometer  $P_1$  has a more slowly change after the switching-on of the motor and can thus be used to reduce progressively the delay  $t$ , thus to cause a smooth start.

Fig. 12 shows a circuit which makes possible a speed control and limitation due to the above described rise-delay for which this delay is controlled by means of a voltage which increases with the speed. As may be seen, this circuit has components ( $R_g$ ,  $D_t$ ,  $R_c$ ,  $C_t$ ,  $ST$ ) which correspond to those of fig. 11 and which have been described in connection with this figure.

However, the capacitors  $C_t$  are charged or discharged by means of two pairs of diodes  $D_+$ ,  $D_-$ . The positive fraction of the currents which flow through the

capacitors  $C_t$ , charges the integrating capacitor  $C_v$  over the diodes  $D+$  or the resistor  $R_v$  so that their mean charging voltage is proportional to the number of revolutions. The resistor  $R_1$  serves to discharge the capacitors  $C_t$  over the diodes  $D-$ , when the respective outputs  $H_x$ ,  $H_y$  of the Hall sensor 31 are situated on the minus potential. The capacity of this capacitor  $C_y$  and the resistor  $R_v$  are selected so that a voltage  $U_v$  arises on the cathode of the diodes  $D+$ , the mean value of which corresponds to the charging state of the integrating capacitor  $C_v$  (the number of revolutions), which however has a sufficient ripple (which mainly arises due to the voltage drop on the resistor  $R_v$ ) in order to switch the transistor  $T_v$  within the phase duration. The resistor  $R_f$  and the capacitor  $C_f$  serve to filter eventual spurious components from this voltage  $U_v$ .

The charging state of the capacitor  $C_v$ , thus the build-up time of this voltage with the number of revolutions, can be adapted by means of the potentiometer  $P_v$  so that a speed control takes place by means thereof.

Function mode : When the number of revolutions of the motor remains under a value adjusted over the potentiometer  $P_v$ , the voltage on the capacitor  $C_v$  is low enough so that the transistor  $T_v$  does not become conducting even at the beginning of the phase (when the capacitors  $C_t$  are in the charging phase). If the number of revolutions of the motor increases, the voltage on the capacitor  $C_v$  increases and the voltage  $U_v$  on the cathode of the diode  $D+$  too. (The resistors  $R_c$ ,  $R_v$  and the capacitor  $C_t$  form a voltage divider).

The voltage  $U_v$  at this moment has the highest value because the capacitor  $C_t$  corresponding to the phase to be switched is discharged at the beginning of the phase. The transistor  $T_v$  becomes conducting at the beginning of the phase and locks the conducting polarized transistor  $T_e$  of the Schmitt-trigger so that the output transistor  $T_a$  thus becomes conducting.

The gate electrodes of the power switches 21 so remain connected with the earth and the power switch is locked. If the voltage on the capacitor  $C_t$  increases after a delay  $t$ , the voltage  $U_v$  drops sufficiently so that the transistor  $T_v$  is locked. Thus, the output transistor  $T_a$  is also locked and the corresponding power switch 21 becomes conducting after the delay  $t$ . This process is repeated for each phase and the delay  $t$  takes up a value because of the described

processes which corresponds to the adjusted number of revolutions. Because the charging voltage of the capacitor  $C_v$  influences the main current, the load state of the motor, which also depends on the number of revolutions, can be reduced or controlled by the increase of this voltage.

Here, further control influences can thus have a voltage increasing or reducing effect. As explained above, the status of the machine can be controlled by different parameters, depending on the gate electrodes  $G_x, G_y$  of the machine. Considering the circuits according to fig. 11-13, it is however more simple to obtain the functions described under a) to f) by influencing the control parameters not directly but at the input of the level switch  $ST$  or at the input of the driver components of the individual phases.

Fig. 13 shows a further circuit where principally the function of the Schmitt-trigger has been realized with the inverting transistor according to fig. 12 over two special control modules/hase (with threshold value switch function, here Mosfet driver, for example of the Micrel type (Mic 445 1B)).

This alternative allows a better triggering because of shorter switching times, especially of bigger Mosfets or of parallel switched Mosfet groups. For this purpose, the circuit according to fig. 12 has been changed as follows.

Respectively one Mosfet driver  $Dr$ /phase with the inverting output  $O$  connected to the gate replaces the Schmitt-trigger  $St$  and the inverting transistor  $T_v$ .

The diodes  $D_1$  and the pull-up resistors  $R_g$  for the gate electrodes are suppressed because now the outputs  $O$  of the two Mosfet drivers  $Dr_X, Dr_Y$  charge or discharge the gate electrodes  $G_x, G_y$  directly over bidirectional currents.

The outputs of the Hall sensor 31 control the inputs of the Mosfet drivers in such a way that their outputs are „low“. (The switch 21 is locked when the respective output of the Hall sensor 21 (phase commutation) is „high“).

The voltage  $U_v$  (analog speed signal with superposed alternating voltage fraction) has been supplied directly to the inputs of the mosfet drivers  $Dr$  over

the decoupling diodes  $D_e$ . The function is similar to that of the circuit according to fig. 12.

When the output  $H_x$  of the Hall sensor 31 is „low“, the output of the driver  $Dr_x$  is „high“ and the motor starts in flip-flop mode (without control).

If the number of revolutions exceeds a predetermined limit, the voltage  $U_v$  increases and the inputs of the drivers ( $Dr_x$ ) receive momentarily values of the voltage  $U_v$  which are above the input threshold of the drivers (approx. 1.5 V) so that their outputs (the gate electrodes) can become „high“ only after the decay of this voltage, thus after a delay  $t$ , so that the motor works in power control mode.

From the prior art, it is known that a change between motor/generator function (brake) is caused by the phase shifting or commutation between two Hall sensors 31, 31'.

The energy recovery is useful for a driving gear of a vehicle or for an accumulator operated electric tool. The SR motors of the invention can without further measures produce, as a generator, a higher voltage than the voltage of the battery which allowed to reach the number of revolutions. Thus, the realization of the above mentioned function is particularly simple. This takes place most of the time with the switching-off of the power control function which is not much used in generator mode.

Eventually it is sufficient to interchange the output signals of the phase control (low instead of high) in order to reach a brake function by partial back charging of the battery.